

# Crimp Data Chart

Line Test	Line Diameters	Crimp I.D.
40#	.024-.026	.033"
50#	.026-.028"	.038"
60#	.029 -.032"	.044"
80#	.032-.036"	.047"
100#	.036-.040"	.050"
130#	.041-.046"	.060"
150#	.046-.056"	.068"
200#	.056-.060"	.073"
300#	.061-.072"	.085"

Average Mono Sizes